Ex	am	No:	

# GANPAT UNIVERSITY M.Tech. [ME (AMT)] Sem-II **REGULAR EXAMINATION MAY JUNE 2014 3ME204 - PRECISION AND QUALITY ENGINEERING**

## TIME - 3 HOURS

**TOTAL MARKS-70** 

1

12

4

4

4

# **INSTRUCTIONS:-**

Attempt All.

Que-1

0

- 1) All questions are compulsory.
- 2) Figures to the right indicate full marks.
- 3) Make suitable assumptions wherever necessary.

## **SECTION-I**

- (a) Describe the honing process with appropriate figure.
- (b) Explain etching process in micromachining.
- (c)
- Explain in detail magnetic float polishing process.

Que-	1 Attempt All. OR	
	(a) Give the types of micromachining process on 1	12
	(b) Discuss the five major steps of product's life such	4,
	(c) Explain the defect categorization in precision vision	<b>3</b> 44
	inspection & measurement system.	4
Que-2	Attempt All.	
	(a) Explain the laser machining process with appropriate figure	11
	(b) Give the comparison between normal, precision & ultra precision machining	6
	, i state state precision machining,	5
Que-2	Attanua ( ) II	
Yue 1	Attempt All.	11
	(a) Explain in detail about ultra precision machining process.	6
	(b) Describe with figure the laser interferometer.	5
Que-3	Attemnt All	3
0.5	(a) Explain LICA	12
	(b) Give the name of provision G : 1:	4
	(c) Describe in detail about on sin last	4
	c) - control in detain about an air bearing.	4
	Stort noti the stort of the the transmisper system	
	SECTION-II	
ue-4	Attempt All	
	(a) Enlist Jurge 's start C and the	12
	(b) Evaluate the steps for quality improvement and explain them in brief.	4
	(c) Explain the concept of lean manufacturing.	4
	(c) Explain the quality and reliability.	4
•1	Certification process	
ue-4	Attempt All. OR	1
1	(a) What is concurrent engineering? Write down advertee at	12
	(b) "Inspection planning is a part of planning for quelies" D	4
	(c) Describe the basic elements of reliability	4
	or following.	4

## Que-5 Attempt All.

- (a) Define the term "Quality control" and explain its advantages over inspection techniques. (b) Control charts for  $\bar{X}$  and R are maintained.
  - Control charts for  $\bar{X}$  and R are maintained on certain dimensions of a manufactured part, measured in mm. The subgroups size is 4. The values of  $\bar{X}$  and R are computed for each subgroup. After 20 subgroups  $\sum \bar{x} = 412.83$  and  $\sum R = 3.39$ . Compute the values of 3 sigma limits for the  $\bar{X}$  and R chart and estimate the value of  $\sigma$ ' on the assumption that the process is in statistical control. Take  $d_2 = 2.059$ ,  $D_3 = 0$  and  $D_4 = 2.28$

11

5

6

11

5

6

12

4

4

#### Que-5 Attempt All.

#### OR

- (a) What is the meaning of quality of conformance? Explain the factors which influence the quality of conformance.
  (b) A sub-group of 5 items each are taken from a factor formation.
  - A sub-group of 5 items each are taken from a manufacturing process at a regular interval. A certain quality characteristic is measured and  $\overline{X}$  and R values computed. After 25 subgroups it is found that  $\sum \overline{X} = 357.50$  and  $\sum R = 8.80$ . If the specification limits are 14.40±0.40; and if the process is in statistical control, what conclusions can you draw about the ability of the process to produce items within specification? Take d<sub>2</sub> = 2.326.

#### Que-6" Attempt all.

- (a) Describe Taguchi's parameter design and tolerance design briefly.
- (b) Describe robust design with example.
- (c) Explain T.Q.M. operation in brief.

# \*\*\*\*\*\*\*\*END OF PAPER\*\*\*\*\*\*